			2001				2002				2003				2004				2005			
ID	Task Name	Qtr4	Qtr 1	Qtr 2	Qtr3	Qtr 4	Qtr 1	Qtr2 Q				Qtr 2	Qtr3	Qtr 4	Qtr 1	Qtr 2	Qtr3	Qtr 4	Qtr1	Qtr 2	Qtr 3	Qtr 4
1	Begin Outfitting & Service Building Constr.								<b>*</b>	9/30												
2	Scintillator Production & Delivery																					
3	Steel Delivery																					
4	Assembly of Near Detector Planes						•			7												
5	Assemble 1st Quarter																					
6	Assemble 2nd Quarter							<u> </u>														
7	Assemble 3rd Quarter							Ĭ	Н,	ı												
8	Assemble 4th Quarter																					
9	Assembly of Near Racks											ı										
10	Underground Occupancy													•	12/22	!						
11	Spectrometer Plane Installation																<u> </u>					
12	Calorimeter Plane Installation																					
13	Detector Electronics Installation																					
14	Magnet Coil Installation																Ě	ı				
15	Near Detector Installation Complete																4	10/7	7 :			
16	Beamline Commissioning Starts																		<b>•</b> 2	77		